

Evaluation Wheel Excavator		<a href="http://www.mevas.eu">www.mevas.eu</a>	
Customer/location:	/Russia, Suoyarvi	vers 01/14	
Date:	14.01.2015		
Machine / type:	CAT M318D	Hour reading:	7803
Serial No.:	D8W00795	Year:	2012
Inspector:	Andreij	stick length:	2,5m
CE <input type="checkbox"/> A/C <input checked="" type="checkbox"/>	stick ch.valve <input type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	stabilizers <input checked="" type="checkbox"/>
quick coupler: <input checked="" type="checkbox"/>	auto lube <input type="checkbox"/>	auxiliary lines <input checked="" type="checkbox"/>	boom VA <input type="checkbox"/> books <input type="checkbox"/>
<b>cab</b>		cab door	good
seat	good	windows	good
switches	good	wipers	good
gauges	good	floor mats	good
aircon / heat	good	structure	good
<b>engine</b>		fluid level	normal
leaks	none	noises	normal
oil condition	good	blow by	minor
exhaust	good	belts	good
smoke	none	cooling system	good
<b>visual inspection exterior</b>		sheet metal	good
chassis	good	bumpers	good
engine doors	good	outriggers/blade	good
stairs, hand rails	good	lights	good
boom	good	paintwork	good
stick	good	rims	good
<b>hydraulics</b>		boom cylinders	good
hoses & lines	good	stick cylinder	good
pump and valve bloc	good	bucket cylinder	good
swivel joint	none	outr/blade cylinders	good
<b>functional test</b>		suspension lock	good
pins boom	minor play	pump noises	none
pins stick	minor play	slew ring play	none
pins bucket	medium play	brake/park brake	good
boom drift	none	electric system	good
swing drive/brake	good	drive train	good
<b>tools</b>		2nd bucket	none
bucket width	1200	condition	
condition	bottom is dented	coupler	good
<b>tires</b>	% remaining life	size:	10.00-20
front right	50	twin / mono:	twin
front left	50	spacer rings:	<input checked="" type="checkbox"/>
rear right	50	cuts:	
rear left	40-50	solid:	<input type="checkbox"/>
<b>problems, details</b>	probably no EPA		
<i>Rear universal joint is damaged - replacement is required.</i>			
<i>Bucket is worn and needs to be replaced.</i>			
<i>New fuel injectors and injectors are needed.</i>			
<i>Maschine is in good condition for hour level. Limited inspection due ice and snow.</i>			
dimensions for transport L x W x H in meter:		9x2,6x3,3	

Sample Report

Sample Report



D8W00795  
(1).JPG



D8W00795  
(2).JPG



D8W00795  
(3).JPG



D8W00795  
(4).JPG



D8W00795  
(5).JPG



D8W00795  
(6).JPG



D8W00795  
(8).JPG



D8W00795  
(9).JPG



D8W00795  
(10).JPG



D8W00795  
(11).JPG



D8W00795  
(12).JPG



D8W00795  
(13).JPG



D8W00795  
(15).JPG



D8W00795  
(16).JPG



D8W00795  
(17).JPG



D8W00795  
(18).JPG



D8W00795  
(19).JPG



D8W00795  
(20).JPG



D8W00795  
(22).JPG



D8W00795  
(23).jpg



D8W00795  
(24).JPG



D8W00795  
(25).JPG



D8W00795  
(26).JPG



D8W00795  
(27).JPG

The original report comes with approximately 40-50 pictures

Videos can be done on demand

Get in touch with Mevas for an inspection quotation

More details about heavy machinery inspections you can find at

[www.mevas.eu](http://www.mevas.eu)

We are your partner in Europe for inspections of used heavy equipment such as excavators, motor-graders, cranes, bulldozers, concrete pumps and rock drills.