

Evaluation Rigid Dump Truck		www.mevas.eu		
Date:	14-10-201X		version 05/11	
Machine / type:	CAT 775D			
Serial No.:	6KR0036X	Hour reading:	16346.30	
Inspector:	Inspector	Year:	1998	
CE <input checked="" type="checkbox"/>	auto lube <input checked="" type="checkbox"/>	exhaust heat <input type="checkbox"/>	supplemental steer <input checked="" type="checkbox"/>	
A/C <input checked="" type="checkbox"/>	retarder <input type="checkbox"/>	tailgate <input type="checkbox"/>	quick refuelling <input type="checkbox"/>	
cab		cab door	good	
seat	normal	windows	good	
switches	normal	wipers	worn	
gauges	normal	floor mats	damaged	
aircon / heat	good	structure	good	
engine		serial No.	90M0254	
leaks	good	noises	normal	
oil condition	needs replacement	blow by	moderate blow by	
exhaust	good	belts	needs replacement	
smoke	black smoke on start up	fluid levels	good	
cooling system	good	power	good	
exterior		tanks	good	
frames	good but rusty	bumpers	good	
sheet metal	good but rusty	lights	good	
stairs, hand rails	good	paintwork	rust on many parts of machine	
power train		suspension rear	good	
axles & seals	good	universal joints	good	
transmission	good	transmission	good	
suspension front	good	brake disks	normal	
hydraulics		steering cylinders	good	
hoses & lines	good	pumps	good	
lift cylinders	good	steering pilot	good	
functional test		electrics	good	
body lift & pins	good	steering	good	
transmission operating	good	stall test	ok	
brakes	normal	park brake	good	
truck body	rust on many parts of body	cracks	not seen	
welds	OK	tail gate	n/a	
bed condition	normal	side wall condition	normal	
tires	mm or % good	24.00R35	cuts recapped	Serial No.
RHS front	42mm	Boto E4	<input checked="" type="checkbox"/> <input type="checkbox"/>	GCA2HW01
RHS rear outside	00mm	Michelin X	<input checked="" type="checkbox"/> <input type="checkbox"/>	VVU296A2D
RHS rear inside	51mm	Double E4	<input type="checkbox"/> <input type="checkbox"/>	GCHGHS03
LHS front	42mm	Boto E4	<input type="checkbox"/> <input type="checkbox"/>	GCA2HW01
LHS left outside	00mm	Michelin X	<input checked="" type="checkbox"/> <input type="checkbox"/>	
LHS left inside	51mm	Double E4	<input type="checkbox"/> <input type="checkbox"/>	GCJGHS03
problems, details				
<i>Hydraulic pump gasket leaking</i>				
<i>Transmission Pump seal is leaking</i>				
<i>The machine is in good to fair condition. Scheduled maintenance is due and several repairs are required</i>				
<i>Air filter found dirty</i>				
<i>Found all filters installed are genuine.</i>				
<i>Batteries weak</i>				
<i>Floor mat damaged</i>				
<i>Customer Name: Recon GmbH 47051 Duisburg(Germany) for Mr.Scott Denton</i>				
<i>Machines Site: Al Almaniah Heavy Equipment Ras Al Khaimah UAE.</i>				
General condition, Component history:				
<i>Hydraulic Hoses and lines are ok but found oil seepage on few hoses needs replacement of oil seals.</i>				
dimensions for transport L x W x H in meter:		4.73M x 4.35 M x 4.36M		



DSCF2421.JPG



DSCF2422.JPG



DSCF2423.JPG



DSCF2424.JPG



DSCF2425.JPG



DSCF2426.JPG



DSCF2427.JPG



DSCF2428.JPG



DSCF2429.JPG



DSCF2431.JPG



DSCF2432.JPG



DSCF2433.JPG



DSCF2434.JPG



DSCF2435.JPG



DSCF2437.JPG



DSCF2438.JPG



DSCF2439.JPG



DSCF2440.JPG



DSCF2441.JPG



DSCF2442.JPG



DSCF2443.JPG



DSCF2444.JPG



DSCF2445.JPG



DSCF2446.JPG



DSCF2447.JPG



DSCF2448.JPG



DSCF2449.JPG



DSCF2450.JPG



DSCF2451.JPG



DSCF2452.JPG

